United States Of America

Bepartment of Transportation - Federal Abiation Administration

Supplemental Type Certificate

Import

Number SROODOGED

This Certificate issued to

Aerolite GmbH c/o Oppenländer Altenbergstrasse 3 70180 Stuttgart Germany,

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 29 of the Regulations.

Original Product - Type Certificate Number:

Eurocopter Deutschland GMBH

Model: BK-117 C-2

Description of Type Design Change: Installation of Emergency Medical Equipment part number 145121-501 or installation of Emergency Medical Equipment part number 145121-502 as documented in Aerolite Master Document List MDL-06-005, Revision A dated January 17, 2007, or later FAA approved revision.

Limitations and Conditions: Rotorcraft Flight Manual Supplement (RFMS) FMS-506, Revision C dated September 7, 2006, or later FAA approved revision is required. Aerolite Instructions for Continued Airworthiness OPM-506 Revision C dated February 2, 2006, or later FAA accepted revision is required for part number 145121-501. Aerolite Instructions for Continued Airworthines OPM-06-011, no revision, dated October 20, 2006, or later FAA approved revision is required for part number 145121-502.

Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 14, 2006

Date of issuance: February 23, 2006

Date reissued:

Date amended: March 06, 2007



By direction of the Administrator

Scott A. Horn

Acting Manage, Rotorcraft Standards Staff

Aircraft Certification Service

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.